

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (assistant Engineer)
(Re:G.O.Ms.20/70/PWD Dt 23-01-1970)

- | | | |
|---|-----------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|
| 1 | Name of the Officer | Anithakumari M T |
| 2 | Name of the School | Carmel convent English Medium School |
| 3 | Location with the name of education district/sub district | Thiruvalla / Pathanamthitta |
| 4 | Classification of buildings as specified in coloums 4 of the application for fitness certificate and size | |
| | Carmel Block | 44.64 x 21.00 x 3.25 (Three Story) |
| | Chavara Block | 30.6 x 15.00 x 3.40 |
| | St.Joseph Block | 32.20 x 17.26 x 3.80 (Two Story) |
| 5 | Period which the certificate is issued | 2025-26 accademic year |
| 6 | Name of defect if any | |
| | i) Foundation and basement | |
| | ii) Superstructure | Nil |
| | iii) Doors and windows | |
| | iv) Wood work wrought and put up | |
| | v) Roof | |
| | vi) flooring | |
| | g) Miscellaneous etc | |
| 7 | Any major defecta noticed which will render the building unsafe in any manner | Nil |
| 8 | Whethermaintanance works have been done properly | Yes |
| 9 | Whether the structureis sound or not for conducting classes | Yes,the structure is sound for conducting classes under normal wind and weather condition |
- Note 1. The stability of the structure should be examined also with reference to location altitude intencityof wind exposure to flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished seperately with the certificate

Certified that the school was inspected by me on 28.05.2025 and found to be fit to conduct classes for the period 2025-26 the reasons stated above under normal wind and weather conditions.

Thottappuzhassery
29.05.2025



Signature
Designation

ASSISTANT ENGINEER
LSGD SECTION
Thottapuzhassery GP